FORM W-89
(10-1-46)

BUREAU OF BUILDINGS
REPORT OF PLUMBING INSPECTION

Date 12/19/46

Address 3265 N. E. U.S. Grant Place Permit 184197

Lot Blk Add

Owner A. J. Finke

Contractor Barney Thornburg

Stories and class of building 2 story old residence

Toilets	Floor Drains	Beer Cab
Bath Tubs	Rain Drains 1 repl	Refr. Drains
Bath Showers	Fountains	Urinals
Basins	H. W. Tanks	Catch Basins
Sinks	Cesspool	Water Service
Laundry Trays	Dry Wells	Conn. To
Water Permit	Bldg. Pmt.	Sewer Permit

Remarks

Date of First Inspection 11/30/46 Date of Final Inspection 12/2/46

Harold Lund Inspector Harold Lund Inspector.

3265 Mulberry Branch Place

Ryle, CT. Right of Way

Form W-89

3-26 5 NE

BUREAU OF BUILDINGS

REPORT OF PLUMBING INSPECTION

9/26/31

Street and No. 991 U. S. Grant Place Permit No. 98387

Lot Tract 8 Block 1 Addition Fernwood

Owner J. F. Cleland

Contractor J. H. Kaye

Stories and class of building fr. 2 sty dwg.

Water Closets	2	Sinks	1	Urinals	
Bath Tubs	2	Laundry Tubs	1	Slop Sinks	
Basins	3	Floor Drains	1	Shower Baths	1
Rain Drains	7	Connected to		Garage Sumps	
Kind of Vents		Kind of Drains			
No. and Size of Stacks		Connected to	sewer		

Other Plumbing Fixtures 10/3/31 G.W.O. Sewer.
10/7/31 G.W.O. Raindrain

Water Permits 9/13/31 #15775

Date of First Inspection 10/2/31 Date of Final Inspection 12/29/31

G.W.O. Overstreet Inspector. G.W.O. Inspector.

Date of First Certificate Date of Final Certificate

2nd W.C. S&F.
2nd Basin & 1 & W.C.
Shower Bath 4 X 2 Taps Tee.
1 & Basin Tray & 2nd Bath
2" W. roof.
2nd W.C. South 2" roof.
2nd Basin " 2 X 1½ Tee.
2nd Bath " 1½ roof.
Sink 1½ roof.